

AFTN: EKMCYOYX

E-mail: FKO-KTP-F-AIM@mil.dk
www.flv.dk/milaim



AIR COMMAND DENMARK
MIL AIM
HERNINGVEJ 30, DK-7470 KARUP J

MIL AIP SUP
11/26
03 JUL 2026

Instrument Approach Procedures at EKKA effected by WIP:

RWY 09L/27R closed between TWY X and RWY 14/32 due to WIP. Working area is marked with barriers. RWY open for taxi outside working area.

RWY 03/21 closed between RWY 09L/27R and RWY 14/32.

RWY 14/32 closed for take off and landing but open for taxi.

Due to WIP in the vicinity of RWY 09R/27L increase minima for all instrument approaches to circling minima, or sidestep minima for RDAF aircraft only. Request for approach with lower minima must be coordinated with Karup ATC before leaving departure aerodrome.

Note: Other NOTAM and SUP affecting approach minima may be published/active during below mentioned effective period.

Effective dates:

The work is planned in the period 03 JUL 2026 - 15 JAN 2027.

Ref.: MIL AIP AD 2 - EKKA.

Valid until further notice.