

AFTN: EKMCYOYX

E-mail: FKO-KTP-F-AIM@mil.dk
www.flv.dk/milaim



AIR COMMAND DENMARK
MIL AIM
HERNINGVEJ 30, DK-7470 KARUP J

MIL AIP SUP
19/25
11 JUL 2025

Construction work at Karup / Midtjyllands Lufthavn - EKKA

This MIL AIP SUP replaces MIL AIP SUP 17/25.

Due to construction work south of the RWY system at Karup / Midtjyllands Lufthavn - EKKA, the following applies:

- TWY X and TWY W closed south of RWY 09R/27L.
- TWY S closed west of TWY S2.
- TWY S2 closed south of TWY S.

REF: MIL AIP AD 2 - EKKA.

Valid until further notice.